

Pratt & Whitney Canada Inc.
1000 Marie-Victorin
Longueville, Quebec, Canada J4G 1A1
514-677-9411



Pratt & Whitney Canada

A United Technologies Company

May 28, 1998

Letter # 1724002-AL-05

Atech Turbine Components, Inc.
19 Ballard Street
Worcester, MA 01607

RE: Confirmation of the following Repair Development Approval:

Approval of the Facility for weld build-up fuel nozzle bore, patch repair on all sections, dual lips cooling ring replacement, and stitch welded cooling rings replacement of the PW100 Liner - Combustion Chamber - Outer assy of

Dears Sirs:

This is to confirm that,

Atech Turbine Components, Inc.
Worcester, MA

have demonstrated to our satisfaction that they have the necessary knowledge, skills, facilities and controls to successfully perform overhaul of the PW100 Liner - Combustion Chamber - Outer Assy Of, on the following part numbers listed in the appendix. The demonstrated processes are defined as Atech Turbine Components Process number CL-3005E, a signed copy of which has been deposited with the Pratt & Whitney Canada Inc., Overhaul Shop Support. This copy will be the document of reference in any dispute and no changes to, nor deviations from, this process are permitted without the written approval of the Pratt & Whitney Canada Overhaul Shop Support Manager.

The intent of Atech Turbine Components process CL-3005E are reflected in the applicable Cleaning Inspection and Repair Manual. Use of this authorization is subject to compliance with local airworthiness authority requirements. Any subsequent part numbers introduced beyond those indicated in this letter require P&WC's specific approval.


Atech Turbine Components, May 28, 1998, Page 2

Failure to maintain satisfactory controls and quality, to provide adequate service, or to adhere to the executed Repair Process Agreement, could result in loss of this approval and deletion of the supplier's name from the Cleaning Inspection and Repair Manual.


Revalidation of this approval will be required after two (2) year of inactivity.

Yours truly,

PRATT & WHITNEY CANADA INC.



L.M. Trottier
Manager, Overhaul Shop Support
Customer Support



F.R. Dowley, DAA #16
Chief Engineer, DAO #93-Q-01
Customer Support

cc: Messrs. C. Faubert 05BC1
W. levers 01TM4
M. Jaffre 05AK2

APPENDIX #1

3037288(RWK)
3040075(RWK)
3040078(RWK)
3040442(RWK)
3040443(RWK)
3105431-01
3106021-01
3110774-01
3112378-01
3112379-01

REFERENCE

- Atech Turbine Process number CL-3005E, dated April 07, 1998.
- P&WC Substantiation Report 1724002 SR-04